



Figure 47. Metal Spray Deposits on the Third-Stage Turbine Stator Vanes